

M Pollard

Date 07/29/2013

Page 1 of 1

(Please Print)

(Please Print)
D Byrd

To

Lothervill

W.O Number

1165727

Item	COMMENTS
------	----------

1	I am nuts on throw rods loose.
---	--------------------------------

Were Switch In the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO ✓

SPECIAL INSPECTION Yes _____ NO ☒

Reason for special Inspection ?

Woodrow Greenwood
Track Inspector Signature

Supervisory Certification

tion M. Dwyer

TRACK INSPECTION REPORTING FORM

Name Walter W. Bryant

Date 6-30-13

Page 1 of 1

✓ Watchman 0134ycl

Inspected From Luther V. Tre

To Cold Springs

W.O Number NC 4749

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

Track inspection Completed.

Were Switch In the area of Inspected all single operating ☒ Yes ☐ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☒ NO ☐

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ?

Track Inspector Signature

Walter W. Byant

Supervisory Certification

ion M. Bayk

TRACK INSPECTION REPORTING FORM

Name W Greenwood

Date 07/30

Page 1 of 1

(Please Print)

(Please Print)
M Pollard

Cold Spring

Penn - Camden

W.O Number 1164834

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	04+04	04+09		0	E		T306	309	Y	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

1. nine foot crack on concrete slab. Perm line

Were Switch in the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 _____ NO _____

Yes _____ NO ✓

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Woodson Greenwood
Track Inspector Signature

Supervisory Certification

M. Bayk

TRACK INSPECTION REPORTING FORM

Name Walter Bryant
(Please Print)

Date 07-31-13

Page 1 of 1

Watchman

Inspected From

Current

To

Linthicum

W.O Number 114 3963

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

Riding inspection - Track inspection completed.

Were Switch in the area of Inspected Yes _____ NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO ✓

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Walter W. Byrnt

Supervisory Certification

on Al Bayk

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1163963	TEAM TWO - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/27/13 12:41:39 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	GLAM	<input checked="" type="checkbox"/>	07/31/13	06:00:00	02:00:00	8:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	07/31/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name W Greenwood

Date

07/31/2013

Page 1 of 1

(Please Print)

Watchman

M Ballard

Inspected From

Linthicum

To

BWI Crumwell

W.O Number

1163966

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

No new defects noted in area.

Were Switch In the area of Inspected

Yes

☒

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes

NO

☒

SPECIAL INSPECTION

Yes

NO

☒

Reason for special Inspection ?

Woodrow Greenwood
Track Inspector Signature

Supervisory Certification

[Signature]

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order **1163966** TEAM ONE - SECT 5 - CM 355S/488S AND
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARK LT Rail Chain Markers
Work Location
Work Group MTA527
Site LTRAIL
Status COMP
Priority 1
Work Type PM
Crew
Warranty Situation Present? N
Maintenance Alert? ☐

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-####-052

Total Planned Cost 0.00
Total Actual Cost 420.64
Repair Limit Amount
Reported By MTACRON
Reported Date 07/27/13 12:41:50 AM

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download Tasks Filter 1 - 2 of 2Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/31/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WGREENWOOD	<input checked="" type="checkbox"/>	07/31/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Select Labor

Select Planned Labor

New Row